East Dean & Friston
Parish Council

Date: **06 May 2021**

Title: **Report Item 9 – Repairs at the play area**

By: **K Larkin (Parish Clerk)**

Purpose: **To report on authority required for the clerk to pay for maintenance in excess of the budget**

Recommendations: **To delegate the necessary authority to the clerk**

---

1. The rope bridge at the play area is cordoned off, as a rope has come loose. Wicksteed have quoted for the parts needed to repair the equipment, as shown in the list appended to this report. The total is £759.76 plus VAT. This is within the budget of £1,000, but the cost of carrying out the work needs to be added and Wicksteed have not yet quoted for that: it could take the total over budget.

2. The clerk has delegated authority to make payments within budget whilst the council is unable to meet during the lockdown, but the council is requested to grant an over-budget extension in this instance, if required.

3. The work is necessary for safety reasons, and approval is recommended.

Item Code	Description	Unit Price	Qty	Net Total
	Supply the following			
SK-1520	Clatter Bridge Handrail Rope Assembly (1 CompleteSide)	325.00	2	650.00
2176-129	M10 x 50 Pentagon Pin	1.79	12	21.48
2185-047	M10 x 120 Hex Bolts BZP	1.79	4	7.16
2215-508	M10 Stainless Steel Form	0.45	8	3.60
2212-203	M10 Sq Spring Washer A2	0.45	4	1.80
2171-101	M6 x 6 Socket Sets Stainless Steel	0.90	4	3.60
2611-031	Black - Plastic Dome Cup & Cap	0.90	4	3.60
2372-008	Pentagon Key to Suit M10, M12 Button Screw & Safety Fastener	9.00	1	9.00
	Supplementaries			
Carriage	Carriage	59.52	1	59.52

TOTAL EXCLUDING VAT	**£**	759.76
VAT TOTAL	**£**	151.95
TOTAL INCLUDING VAT	**£**	911.71